### DANNY'S CORNER



A very joyous holiday greetings to you and yours; hopefully you enjoyed the season with your loved ones! In lieu of holiday cards, our team donated toys to Holland Bloorview Kids Rehabilitation Hospital.

We are looking forward to a great 2013 in the multi-unit residential industry! Financing rates remain low and we continue to see these rates fueling significant increases in sales values – especially in the GTA - both on a price per suite basis and lower CAP rates. At the time of publishing this newsletter, 5 year financing terms were around 2.4% and 10 year terms were around 3.0%.

I would like to take the opportunity to personally welcome the newest member of our sales team, Anne Meinschenk, as Skyview Realty's Associate Vice President. As you may know, Anne has been actively involved in our industry for over 10 years and will be a great resource to you, our valued clients. You can learn more about Anne's background later in this newsletter.

Over the past while we have had several transactions where Belanger Engineering has been involved. They are known for their expertise in the field of structural engineering. To this end, I have asked them to provide some valuable insight into what apartment building owners should be aware of from an engineer's perspective.

As we enter this new year, I want to reiterate Skyview's on-going commitment to your furthered success in the apartment building sector. If there is anything we can assist you with - whether buying or selling properties - please do not hesitate in contacting myself or one of our Skyview team members. All the best to you in 2013!

Danny lannuzziello

# Got Leaks? What you Need to Know from an Engineer's Perspective by Belanger Engineering

Belanger Engineering carries out Condition Assessments and Repair Planning for buildings and individual building components. Our reports include detailed explanations of existing conditions, recommended repair philosophies/strategies, repair/replacement cost estimates and any other pertinent information that will aid the owner in the decision making process.

There have been a number of occurrences of reported water leakage at properties. We have extensive experience in this area. While each project is evaluated on its unique conditions we have established a protocol that serves us and our clients well in achieving a high rate of success while minimizing related costs.

Our work typically begins with a visual review of the suite interiors or common element areas at the reported leak locations. An initial assessment is made, and the point of water evidence is recorded. From our perspective, we gain greater knowledge from the owners and staff as they are able to provide valuable details that will help with our initial assessment.

The pattern of leakage is often instrumental in solving leakage issues. By way of example, valuable information can be gleaned based on the history of the leakage. Leakage that suddenly develops is often the result of changes in material conditions and we focus initially on sealants, waterproofing membranes or other components such as roofing materials that may have been damaged/deteriorated resulting in the leakage events.

Terraced properties often experience persistent leakage at the terraced areas simply due to the interruption of the exterior building walls at each such terrace. Water that penetrates into the wall assembly above a terrace can flow downward through the wall

assembly until it is obstructed by the terrace floor slab. In these cases addressing the point(s) of water entry can provide immediate relief to the leakage; however, subsequent sealant or material failures can be expected to once again cause leakage into these suites.

In many cases, flashing changes can be done to minimize or prevent such persistent damages to the interior and the related inconvenience and disruption to the residents.

Minor leaks can go unnoticed by owners for long periods of time until they manifest in visible damage into the interior finishes, such as stained hardwood, stained carpets and drywall damage. Minor leaks are often the most difficult to detect. In our experience water testing is not often the most cost effective way to handle minor leaks as the water penetration is not readily detectable unless the interior finishes are removed.

We try to provide owners with knowledge on how to prevent certain types of leakage. For example one common mistake owners make is leaving their exterior sliding windows open while closing the interior slider only. Doing that during a rainfall allows the water to directly penetrate the sliding window tracks and enter the wall systems.

Many owners believe that shutting the interior sliding window is ok; however, most are not aware that the two sliding window tracks are designed differently. The exterior window tracks are fitted with drains so that water is directed to the exterior of the building. The interior sliding window tracks are not fitted with drains, therefore allowing the water to be trapped and accumulate.

...Continued on Page 2

IF YOU ARE THINKING OF BUYING OR SELLING, PLEASE CALL (416) 444-6545 FAX (416) 444-6997



### **Skyview Welcomes Anne Meinschenk!**

Anne is a graduate from the University of Guelph with an Honours B.A. It was at University that Anne first began her professional sales career working for a direct sales organization and finding clients by personal referral. Realizing her passion lay in building lasting relationships Anne set out to make professional sales her permanent career. Anne has spent the past 11 years working directly with owners of multi-family investments developing an extensive network of clients and contacts.

Anne has been a member of the Federation of Rental Housing Providers of Ontario (FRPO), the Multiple Dwelling Standards Association (MDSA) and the Hamilton District Apartment Association (HDAA) for 11 years. These organizations work directly to support owners of rental apartment assets.

Anne is ecstatic to join the Skyview Team in her role as Associate Vice President and Sales Representative.

### Got Leaks?

(Continued from Page 1)

This condition can result in an overflow of rainwater at the window track resulting in damage to the interior. In addition, over time the serviceable lifespan of the internal window seals are reduced due to prolonged exposure to moisture. The seals deteriorate and breakdown which results in leakage and ultimately leads to replacement of windows being required.

Condensation and condensation damage is also a major concern for most owners. Some condensation is expected in units and is considered normal.

Most typical hi-rise residential buildings are equipped with makeup air units located on the rooftops. These units supply conditioned air to the corridors. This air is normally a few degrees cooler than the interior air of the building. This supply of cool/dry air absorbs moisture as it passes through the units and dispels the moisture to the exterior by bypassing the seals at the sliding windows. Moisture is also exhausted through the kitchen, bathroom and dryer vents.

A few tips to alleviate excessive condensation are as follows:

- Don't install seals around the perimeter of the suite entry doors as this restricts the supply of makeup air into the suite resulting in excessive buildup of humidity;
- Ensure the exterior and interior sliding windows are fully closed and engaged at the interlocks;
- Operate the dryer exhaust fan while doing laundry;
- Ensure the dryer lint trap is clean and maintained in a clear condition:
- Ensure the lint trap in the duct work is maintained in a clear condition;
- Operate the exhaust fans in the washrooms while in use and for at least one half hour after bathing;



This building was sold by Dani Pizzoferrato of Skyview Realty Ltd, Brokerage. The property is located in York near Dufferin and Rogers. Close to TTC, shopping, and schools the property was easy to rent to potential tenants. The building experienced little vacancy. Within the past 5 years, three of the 1 Bedroom suites were converted to 2 Bedrooms. Many other units in the building had been updated and/or renovated in flooring and kitchens.

- Operate the kitchen exhaust fans while cooking (if so equipped);
- Minimize the use of humidifiers, steamers, rice cookers, etc. and at times when excessive condensation issues are present.

Belanger Engineering takes great pride in helping to address our clients' needs and providing safe living conditions for all owners. We focus on expanding our value to our clients and their agents by providing holistic building science solutions.

We promote and ensure the superior delivery of consulting services so our customers experience excellence every time.


Belanger Engineering Team 1060 Britannia Road East, Unit 23 Mississauga, ON L4W 4T1 Phone: (905) 795-9997 Web: www.belangerengineering.ca



- Individual Hydro Meters
- · Thermo Windows & Patio Doors
- · Upgraded Balconies with Water Protection Layer
- Good Suite Sizes and Layouts
- · Good Tenant Profile

- **NIAGARA FALLS** 10 MINUTES AVAILABLE ROM FALLS Principals Only Please 36 Suites 1 x Bachelors Asking \$77,778 per suite
- - . Located in the Suburb of Chippawa only a ten minute drive to Tourism Area
  - Recent Improvements include Thermo Windows, Patio Doors
  - Balcony Waterproofing
    Heat and Hydro Paid by Tenants Some Units Upgraded with
  - Laminate Flooring

    Ample Surface Parking
- 7 x One Bedrooms
- 16 x Two Bedrooms
- 12 x Three Bedrooms Good Tenant Profile in a Quiet
- Neighbourhood 6 2% CAP Rate
- 14.5% R.O.I. Ex. 1st Mortgage for approx. \$1,740,000 @ 3,61% due April
- 2016 to be Assumed VTB Available to Buyer



- Asking \$3,360,000
- Asking \$124,444 per Suite
- Located in South Etobicoke close to all amenities
- Surface Parking + Garages Thermal Windows
- Roof in Good Condition
- Hydro paid by Tenants
- Some units have been renovated with new flooring and kitchens
- 7 x One Bedrooms 16 x Two Bedrooms
- Good Tenant Profile in a Quiet Neighbourhood
- Good Superintendent Couple on Site 5.1% CAP Rate
- Potential Upside on Rents
- Existing 1st Mortgage of approx. \$1,700,000 @ 3,43% due January 2021 to be Assume

## **TORONTO (EAST YORK)**



### 12 Suites + 6 Commercial Units

- Asking \$3 650 000
- Property contains 12-2 Bedroom
   Duplex Apartments each with 2 washrooms
- 6 Commercial Units on the Ground Floor
  Built in the 1990's
- Potential Upside on Rents
- Located just North of Danforth on Favourable Intersection, close to Subway
- 12 x Two Bedrooms
   6 x Commercial

Fire Retrofit Completed

due in 10 years, to be

Assumed

VTB Available to Buyer

• Ex. 1st Mortgage @ 2.85%

• 6.2% CAP Rate • 19.2% R.O.I.

- Existing First Mortgage for 80%
   @ 3% due Jan 2021 + 5 year option @ 4%
   \$250,000 VTB Available @ 4%

- 6 x Commercial

  Residential Tenants pay for own
  Heat & Hydro, Commercial Units Pay
  Own Utilities

  5.7% CAP Rate

  22.9% R.O.I.

# UPSIDE POTENTIAL

**TORONTO** 

### Principals Only Please 29 Suites

- Asking \$2,465,000
- Asking \$85,000 per Suite
- Well Maintained and Landscaped Property Located in the Heart of Toronto (York) Located Close to Transit,
- Shopping, and Residential Neighbourhood
- Possibility to Convert Tenants to Individual Meters
- 18 x One Bedrooms 11 x Two Bedrooms Double Membrane Roof
- New in 2008 Thermo Windows
- Terrazzo Flooring in Hallways 6.7% CAP Rate
- 27.4% R.O.I.
- Treat Financing as Clear
- Seller May Consider VTB to Sell

### **NORTH YORK** OCATED NEAR POTENTIAL NEW HOSPITAL UPSIDE

### Principals Only Please 10 Suites

- Asking \$1,298,000
- Asking \$129,800 per SuiteLocated near Jane and Wilson
- close to the New Humber River Hospital being Built
- Upgraded to Thermo Windows
- less than 2 Years Ago Tenants Pay Own Hydro -Individually Metered
- 2 x One Bedrooms 8 x Two Bedrooms
  - Capital Items in Good Condition
- Potential Upside on Rents and Potential to Add Additional
- Bachelor Unit in Basement
- TTC Bus Stop at Doorstep
- 18.8% R.O.I.
- Treat Financing as Clear



- Asking \$799,000 Asking \$79,900 per Suite including
- the two Commercial units.
- Nicely kept Apartments Very close to new Shopper's Drug Mart, Pizza Hut, McDonalds and Tim Hortons
- Tenants pay own utilities (except unit) including Heat, Hydro and Corner Property on Main
- Thoroughfare
- 8 x 1 Bedrooms
- Property is already severed into two (2) parcels.
- 6.9% CAP 20.6% R.O.I.
- Treat property financing as clear
   Seller willing to hold a second mortgage for 10% of the
- purchase price for qualified

## **NIAGARA FALLS** 8.5% CAP RATE! Principals Only Please 11 Suites

- Asking \$705,000
- Asking \$64,091 per Suite
- Located Five Minutes from Casinos/ Tourism Area, in a Quiet Residential Neighbourhood Vinvl Thermo Windows (2006)
- New Roof Shingles in 2009 Property consists of Two Four Plexes and One Triplex
- 1 x Bachelor
- 2 x One Bedrooms
- 6 x Two Bedrooms
- 2 x Three Bedrooms Apartments are Spacious and Feature Laminate Hardwood
- 8.5% CAP Rate 30.4% R.O.I.
- Treat Financing as Clea Seller May Consider VTB to
- Qualified Buver



- Semi-Detached Bungalows & One Six-Plex
- Under New Management with Many Improvements Being Done
- Some Rents are Below Market.
- Potential Upside New Tenants Paying All their Own Utilities on Turnover
- Tenant Profile
- Waterfront Property on Bay of Quinte with Boat Launch
   Good Amount of Excess Land
- at Rear of Property . 8.3% CAP Rate
- 30.4% R.O.I.
- Treat Financing as Clear!

# industry report

trends and services

OMMENDED SERVICES

### WEEKLY E-MAIL BLASTS

Sign-up and begin receiving:

- Weekly Multi-Residential
- Property Listings Industry Related Articles News, Resources, and Valuable Links
- Updates on Sold Properties in Your Area



Send us Your Email Address Today! info@skyviewrealty.com 416-444-6545

### Michael Lombard

Vice-President Regional Manager - Ontario


Telephone: 416.368.3266 Facsimile: 416.368.3328 michaell@peoplestrust.com www.peoplestrust.com



Suite 1801 130 Adelaide Street West Toronto, Ontario Canada M5H 3P5

"Innovative Financial Products with Exceptional Client Services"

RESIDENTIAL	RECE	NT TRAN	SACTION	<b>S</b>
Sep	. 17, 2012	13 Units @	\$126,538	\$ 1,645,000
Sep	. 28, 2012	24 Units @	\$100,000	\$ 2,400,000
Oct	02, 2012	47 Units @	\$95,745	\$ 4,500,000
Oct	. 03, 2012	76 Units @	\$190,282	\$14,461,400
Oct	. 04, 2012	20 Units @	\$146,250	\$ 2,925,000
Oct	. 11, 2012	32 Units @	\$59,375	\$ 1,900,000
Oct	. 17, 2012	108 Units @	\$81,481	\$ 8,800,000
Oct	. 19, 2012	16 Units @	\$106,250	\$ 1,700,000
Oct	. 22, 2012	60 Units @	\$116,667	\$ 7,000,000
Oct	. 26, 2012	42 Units @	\$121,429	\$ 5,100,000
Oct	. 31, 2012	77 Units @	\$140,260	\$10,800,000
Oct	. 31, 2012	77 Units @	\$141,558	\$10,900,000
Oct	. 31, 2012	116 Units @	\$94,397	\$10,950,000
Oct	. 31, 2012	90 Units @	\$151,111	\$13,600,000
Oct	. 31, 2012	78 Units @	\$185,256	\$14,150,000
Nov	. 01, 2012	22 Units @	\$140,909	\$ 6,200,000
Nov	02, 2012	18 Units @	\$86,667	\$ 1,560,000
Nov	. 07, 2012	82 Units @	\$85,976	\$ 7,050,000
Nov	08, 2012	28 Units @	\$100,000	\$ 2,800,000
Nov	. 08, 2012	272 Units @	\$227,206	v\$61,800,000
	Sep Sep Oct	Sep. 17, 2012 Sep. 28, 2012 Oct. 02, 2012 Oct. 03, 2012 Oct. 04, 2012 Oct. 11, 2012 Oct. 17, 2012 Oct. 19, 2012 Oct. 22, 2012 Oct. 26, 2012 Oct. 31, 2012 Nov. 01, 2012 Nov. 02, 2012 Nov. 07, 2012 Nov. 08, 2012	Sep. 17, 2012       13 Units @         Sep. 28, 2012       24 Units @         Oct. 02, 2012       47 Units @         Oct. 03, 2012       76 Units @         Oct. 04, 2012       20 Units @         Oct. 11, 2012       32 Units @         Oct. 17, 2012       108 Units @         Oct. 19, 2012       16 Units @         Oct. 22, 2012       60 Units @         Oct. 26, 2012       42 Units @         Oct. 31, 2012       77 Units @         Oct. 31, 2012       77 Units @         Oct. 31, 2012       78 Units @         Oct. 31, 2012       78 Units @         Nov. 01, 2012       22 Units @         Nov. 02, 2012       18 Units @         Nov. 07, 2012       82 Units @         Nov. 08, 2012       28 Units @	Sep. 17, 2012       13 Units @ \$126,538         Sep. 28, 2012       24 Units @ \$100,000         Oct. 02, 2012       47 Units @ \$95,745         Oct. 03, 2012       76 Units @ \$190,282         Oct. 04, 2012       20 Units @ \$146,250         Oct. 11, 2012       32 Units @ \$59,375         Oct. 17, 2012       108 Units @ \$106,250         Oct. 19, 2012       60 Units @ \$116,667         Oct. 22, 2012       60 Units @ \$121,429         Oct. 31, 2012       77 Units @ \$140,260         Oct. 31, 2012       77 Units @ \$141,558         Oct. 31, 2012       116 Units @ \$94,397         Oct. 31, 2012       90 Units @ \$151,111         Oct. 31, 2012       78 Units @ \$185,256         Nov. 01, 2012       22 Units @ \$140,909         Nov. 02, 2012       18 Units @ \$86,667         Nov. 08, 2012       28 Units @ \$100,000         Nov. 08, 2012       272 Units @ \$227,206



## **SkyViews**

### Winter 2013

### PUBLICATION:

Our newsletter is published quarterly: (January, March, June, and September). ADVERTISING:

For advertising rates and article suggestions, please contact the marketing department or email info@skyviewrealty.com

Please refer to our website for our Privacy Policy Statement. If you wish to be removed from our mailing list, kindly advise us by fax, e-mail, or telephone.

### THE SKYVIEW TEAM

419-220 Duncan Mill Rd., Toronto Ontario M3B 3J5 (416) 444-6545 Fax: (416) 444-6997 Email: info@skyviewrealty.com

### www.SkyviewRealty.com

All information furnished regarding this newsletter or information contained herein, is from sources deemed reliable, but no warranty or representation is made as to accuracy thereof and the reader is advised to seek independent legal, accounting, or any other consulting advice as may be deemed necessary. Any property information may not be used in advertising on any third-party platforms without the written consent of Skyview Realty Ltd, Brokerage.



